

New Seal Seat Material and Warranty for All C-Model Regenerative Turbine Pumps

New silicon carbide seal seat

In an ongoing effort to improve product performance and durability, Corken has upgraded the seal seat material for all C-Model regenerative turbine pumps to silicon carbide. The new material reduces leakage, improves durability, minimizes maintenance, and lasts longer. Listed below are more details on this change:

- Effective October 3rd, the standard seal seat material for all C-Model regenerative turbine pumps has been upgraded to silicon carbide.
- The specification field for the seal material changes from a “2” to a “6” (e.g. if you typically purchase a C12FD~~2~~A pump, the new model number for the silicon carbide seal seat material is C12FD~~2~~**6**A).
- There is no additional charge for the silicon carbide upgrade.
- Cast iron seal seats are available until all inventory is depleted.
- The new part number for the silicon carbide seal assembly is 113-CXA~~6~~. The old cast iron seal assemblies (p.n. 113-CXA) are available while supplies last.

A better seal seat material and a stronger warranty at no additional charge.



New extended three-year warranty

All C-Model pumps ordered with the new silicon carbide seal seat get an extended three-year warranty with no additional charge. This warranty supersedes all previously offered C-Model warranties. Listed below are the details for the new three-year warranty:

CORKEN, INC. warrants that all C-Model pumps with the silicon carbide seal seat will be free from defects in material and workmanship for a period of three years from date of installation, provided that the warranty shall not extend beyond four years from the date of shipment from CORKEN.

Solutions beyond products...

CORKEN®

CORKEN, INC. | A Unit of IDEX Corporation
3805 N.W. 36th Street | Oklahoma City, OK 73112 U.S.A.
Phone: 405.946.5576 | FAX: 405.948.7343
Visit our website at www.corken.com
E-mail us at cocsalesdept@idexcorp.com



@CorkenInc

